

- Please read instructions completely prior to installing the level. 1.
- The mounting surface should be relatively flat. 2.
- 3.
- The mounting surface should have three tapped holes 120° apart. Position the piece of equipment on to which the level is to be mounted in a level 4. position with respect to the horizontal plane.
- 5. Attach the level and spring to the mounting surface using three screws as shown above.
- Be sure to tighten the screws evenly to avoid damaging the level. 6.
- 7. Adjust the level into the level position by tightening or loosening screws until the bubble is in the center of the centering circle.
- 8. To insure the level does not move due to loose mounting screws, apply a thread locking material to the screws. Use a non-permanent thread locking material if you wish to remove and/or replace the level at a later date.

© Copyright 2009 by	<u>)</u>
9 New Turnpike Road, Trov, NY	12182